

The class is subject to the starboard screwshaft and tubeshaft being further examined and dealt with by May 1958, and to the port screwshaft and tubeshaft being examined and dealt with by February, 1959.

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

24 JUN 1958 4E

LUCANIA

NAME.....

REPORT Gen

No. 23305

ES due 6.57, partly held 2.57, now completed.

MBS due 5.58, partly held now.

SRL: The starboard screwshaft and tubeshaft examined and the Surveyor recommends that both shafts be renewed by the end of May 1959.

ALTERATION: A new desuper-heater, in place of the original, has now been fitted, and the Surveyor recommends the new installation be examined under working conditions on the vessel's return to Genoa from the present voyage.

IT IS SUBMITTED this vessel is eligible to remain as classed with fresh records of ES 2.57 now, and MBS 4.58 when the survey has been completed, subject to the starboard screw and tubeshafts being renewed before the end of May 1959, also to the new de-superheater installation being examined under working conditions on the vessel's return to Genoa from the present voyage (2 months' limit). //

NB. It is considered that the record of TS (CL) Starboard 4.58 should be withheld.

NOTE. PLANS DEPARTMENT to check.

Noted JF
24/6/58

20.6.58



© 2021

Lloyd's Register
Foundation

003687-003697-0283

Date of Committee.....

THURSDAY 26 JUN 1958

Noted