

COPY.

LLOYD'S REGISTER OF SHIPPING,  
HULL, 29th August, 1934.

RECEIVED  
30th August, 1934.

Dear Sir,

With reference to the query contained in your classing letter of the 28th instant concerning the size of rivet holes in the boiler shells of the steam trawlers "LORD HAILSHAM", report No.45046, "LORD LLOYD", report No.44054 and "BAYFLOWER" report No.43901, we have to state that these are  $1 \frac{3}{8}$ " diameter and not  $1 \frac{3}{32}$ " as stated in our reports.

The size of rivet holes in the boiler shell of the steam trawler "SOLON", report No.41579, is  $1 \frac{9}{32}$ " diameter as previously stated.

It is regretted that the sizes stated in the three former cases were in error.

We are, Dear Sir,

Yours faithfully,

The Surveyors.

The Secretary,

LONDON.



© 2020

Lloyd's Register  
Foundation

003698-003705-0022

