

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

11th December, 1937.

VESSEL'S NAME

Single Sc. M.V. "SAINT EUNAN" Report

No. 59120

Dear Sir,

S.

With reference to Glasgow Report No. 59120 on machinery for the motorship "SAINT EUNAN", I have to say that it is concluded that a spare power driven lubricating oil pump is fitted: also that the small auxiliary engine can be started by hand for first charging the air receivers but I shall be glad if you will ascertain from the Surveyors and let me know whether this is so.

I am, Dear Sir,

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
GLASGOW.



© 2020

Lloyd's Register
Foundation

thickness of Intercoastal Plate...

Angle

Single.

6 3 46

Spacing