

2m.10.43.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "SAINT EUNAN" REPORT Gls No. 68153

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey..... Damage ~~Wxxxxx~~

Subject to indented shell plate D.7 (p.s.) being dealt with at the Owners convenience, and to permanent repairs to indented bottom plating etc. at the first convenient opportunity.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

was
7-3-44



© 2020

Lloyd's Register
Foundation

003706-003711-0038

Transverse.....	efficient? Not examined	Breasthooks & Stemson.....	Stated length.....
Floors Exd. in No. 1 hold-Good	Have Watertight Doors been examined and found.....		