


grams: Nymdible, New York

Telephone WHitehall 4-0220



Please address
further communications
on this subject to
PRINCIPAL SURVEYOR

AIR MAIL

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

17 Battery Place,

New York 4, N. Y.

RECEIVED

-1 FEB 1954

January 28, 1954

0209

ssn.S.

DONKEY BOILER SPACE

WORKING FLOOR

Dear Sir:

"REGENT JAGUAR"

Referring to your letter of the 7th instant regarding the above mentioned case, the Surveyors advise that the two bolts which replaced the two defective shell rivets are at the flange of boundary bar of the Donkey Boiler space flat (starboard side) as per sketch herewith.

The Surveyors also confirm that the examination of the Nos. 4, 6 and 7 main engine crankshaft journals may, in their opinion, be credited towards the Continuous Survey.

Yours faithfully,

Secretary to the American
Committee

The Secretary,

LONDON



© 2020

Lloyd's Register
Foundation

003706-003711-0208-1

CLASSIFICATION

H

LONDON

The Secretary,

Committee
Secretary to the American

Yours faithfully,

opinion, be credited towards the Contingents Survey.

nos. 4, 5 and 6 main engine crankshaft journals may, in their

The Surveyors also confirm that the examination of the
(starboard side) as per sketch herewith.

the flange of roundly part of the Donkey Boiler since that
ports which replaced the two defective shell rivets are at
the above mentioned case, the Surveyors advise that the two

Referring to your letter of the 17th instant regarding

Dear Sir:

"RECENT ADVANCE"

LIAISON

JANUARY 28, 1954



RECEIVED

New York 4, N. Y.

17 Battery Place,

UNITED WITH THE BRITISH CORPORATION REGISTER

LLOYD'S REGISTER OF SHIPPING

12: 10/11/54

12: 10/11/54