

The class is subject to the condenser waterboxes being renewed before the end of 10.57.

4E

14 NOV 1957

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

VNAME....."REDRIFF"..... REPORT..... Nwc..... No114786.

MBS due 10.57, now held.

Docking. Screwshaft seen.

SRL : The above item now dealt with. To be deleted.

Some boiler repairs now carried out.

RECORDS, IT IS SUBMITTED that this vessel is eligible for THE  
MBS 10.57,  
TS(CL) 10.57, without special condition.

*DM*  
11.11.57.



© 2020

Lloyd's Register  
Foundation

005788-005799-0045