


Engine Kumasi

Exs. 69178

It is noted from dynamo test sheets that the high voltage test is given as 1500 volts. As the requirements of the Rule call for 2000 volts for this size of machine the Surveyor remarks are awaited before the Case receives confirmation.

Some of the particulars for boiler & Superheater omitted from Ex report 68149 should be forwarded.

See Ex letter 23.1.45



© 2020

Then  
15.1.45

Lloyd's Register  
Foundation

003788-003799-0162

boiler  
17/11