


## LLOYD'S REGISTER OF SHIPPING

Port Lagos.Date 2nd December, 1964.

This is to Certify that I have surveyed the s.s. "MULBERRY HILL" 7,121 Gross tons of London for damage to starboard bow plating and internals in the lower peak space,

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be continued as classed without fresh record of drydocking subject to any outstanding conditions of class and subject to starboard shell plates SJA4, SJA5 and SJ18 and internal structure in way being specially examined and dealt with as necessary at next drydocking.

H. Pollock,  
Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 150m,7,62 (MADE AND PRINTED IN ENGLAND.)

003808-003815-0144