

5m,12,46.

CW

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

30 SEP 1948

VESSEL'S NAME GOLDFINDER

REPORT

Cff.

No. 56191

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs to stem and stem plating, (side shell plating (s.s.f) and bilge strake (p.s.) at the first convenient opportunity.

The CARDIFF Surveyors report the vessel placed in dry dock, bottom coated and minor repairs effected.

The after peak tank has now been converted to a temporary reserve oil fuel bunker in accordance with approved plans. Indented plating, etc. as above examined and continues efficient.

It is submitted the vessel is eligible to remain as classed, with record of docking 8.48, subject as above.

8.48 Cff. subject.

100.1.
24.9.48.



© 2021

Lloyd's Register
Foundation

003838-003845-0110