

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic (Inland: Committee, London, Telex
Address) Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

ENCLOSURES

14th February, 1964.

C
DHGK/CB

Dear Sirs,

Steamer "FILIA"

Further to the telephone conversation between Mr. Boylan and Mr. Todd yesterday I enclose a copy of Hamburg Report No.13302 and a translation of the D.S.R.K. Report for your information and guidance.

The hull conditions of class are as follows:-

"Stem and stem plating being specially examined and dealt with as necessary by the Special Survey, to shell plates No.1 in 3rd strake below and No.6 in 2nd strake below sheer (port side forward) being specially examined and dealt with as necessary on arrival at Genoa via Hamburg from the present voyage, and to shell plating in way of No.4 hold (starboard side) and all 'tween decks, hatchways etc., being specially examined and dealt with as necessary in drydock on arrival at Genoa from present voyage".

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Surveyors,
GENOA.



© 2021

Lloyd's Register
Foundation

005838-003845-0198