

EA

Ship's name "FILIA" Port HAM No. 13302

Class is subject to stem and stem plating being specially examined Last survey date 22.1.64.

and dealt with as necessary by the S.S., and to shell plates No.1 in 3rd strake below and No.6 in 2nd strake below sheer (p.sf) being specially examined and dealt with as necessary on arrival at Genoa via Hamburg from present voyage.  
ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat and ~~in drydock~~)

Examination afloat in loaded condition on account of damage stated caused whilst loading steel cargo at Wismar.

Recommendation SUBJECT as above and to shell plating in way of No.4 hold (s.s) and all tween decks, hatchways etc. being specially examined and dealt with as necessary in drydock on arrival at Genoa from present voyage, but ACTION continue to be DEFERRED for examination in drydock after grounding.

SUBJECT.  
IN S.R.L.  
Drydocking (~~g~~rounding).

IN S.R.L.APPENDIX  
Keel plate in way of E.R. slightly wavy.

NOTE: Genoa Surveyors have been advised.

Ship reported under survey at Genoa 7.2.64.

Ship Plans .....

Ship Reports .....

Ship's Documents .....

TO NOTE

© 2021

Lloyd's Register  
Foundation

2/3/64