

25 MAY 1957

Received from Chief Ship Surveyor

SHIP'S NAME

"LUCIA"

REPORT

Cco.

No. 5094

Outstanding Conditions of Class:

Subject to set up bottom and indented side plating being examined and dealt with, if necessary, at the next drydocking, and to one bower anchor on board being tested to Rule requirements at the earliest opportunity.

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Damage (collision) involving stem plating etc. (p.s.) -  
temporary repairs.

Recommendation:

SUBJECT as above, and to permanent repairs to stem plating etc. (p.s.) next drydocking.

As Now. Subject

OFFICE NOTE

Shell and deck transverse  
butts reinforced - Cco. 2,53.



© 2021

Lloyd's Register  
Foundation