

14 SEP 1961

Received from Chief Ship Surveyor.....

SHIP'S NAME "NEVERITA" REPORT Rot. No. 52110  
GB

Outstanding Conditions of Class: SUBJECT to fractured shell plating in way of No.6 cargo tank (s.s.) and 2nd strake below sheer in way of stokehold (p.s.) being specially examined and dealt with as necessary by 7,61.

S.R.L. Appendix. (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (C) due 6,61.

Nature of Present Survey: (~~Aft~~ ~~at~~ ~~and~~ in dry dock)

Docking: Temporary damage repairs.

Special Features: See also Ship Research Endorsement dated 15.2.61 and subsequent correspondence re repairs.

Is Interim Certificate in order (Yes-~~No~~-~~None~~)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

S.S. to be completed by:

Recommendation:

SUBMITTED record of 'DS 7,61' be assigned as recommended, subject as above, and to keel plating in way of aft end of E.R. being specially examined and dealt with as found necessary by the Special Survey, but ACTION be DEFERRED for Special Survey.

DS 7,61 Subject

IN S.R.L. APPENDIX.

Shell plates B.5,6,8,10,12 & 14 (s.s.)  
B.9 & 15 (p.s.) (all from aft) A.3 (p.s.f) and keel indented.

Now laid Up R. Blackwater.



© 2021

Lloyd's Register Foundation