

ouge Johanna

Rot-17945

It is concluded that the stroke
of the engines is 1000 rpm, not 285 rpm
as reported & that each Boiler safety
valve is 60 rpm in diameter but the
Surveyors should confirm this.

W.D.

B.F.

14/11/28

Lloyd's Register
Foundation