

2 JUN 1955 4E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME "JUPITER" REPORT Ham. No. 3871.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/52.)

of Survey REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH
screwshaft breaking.

Docking. Screwshaft found broken at the large end of the taper in way of liner, and the shaft now changed.

It is stated that the BS. due 4,55 will be held on the vessel's arrival at Amsterdam.

IT IS SUBMITTED that this vessel is eligible for the Record S. 4,55.

© 2021

Lloyd's Register
Foundation

FOR C.E.S.
RECORDS
TO NOTE

1 JUN 1955

005838-005845-0337