

COPY

# LLOYD'S REGISTER OF SHIPPING



Miami, Florida

Port November 17, 1961

Chilean M/V ~~SR~~ ~~VERONICA~~ **This is to Certify** that I have

~~Surveyed the~~ vessel lay afloat at Miami, Florida, on October 30, 1961, and subsequently while docked on the floating dock of Dade Drydock Corporation, Miami, Florida, in consequence of damage alleged to have been sustained when the vessel landed alongside the south jetty at Miami on October 30, 1961,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed ~~to my satisfaction, also that I will~~ **Recommend that she be** ~~admissible in my opinion to remain as~~ **Recorded in the Register Book without fresh record of survey.**

Fred H. Hallbauer

Surveyor to Lloyd's Register.

No. 368

### KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	SS(P)	Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”

(Cert. B) 15M 8-59 PRINTED IN U. S. A.

003846-003857-0082

© 2020

Lloyd's Register Foundation