

11 SEP 1954

as in the Register Book

HULL	MACHINERY
+100A1 with freeboard 7-53.	+LHC 9-52 BS. 7-53 TSC 7-53 SPS 9-52
SSLH 9-48 (2Y) CSLIV 9-52	

Vessel in dry dock. Examination made of propeller
after end of stem broken and underbelly fastenings.

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, etc.)

The machinery of this vessel is in my opinion eligible to remain as classed without fresh record of Survey.


T. H. H. H.
Engineer Surveyor to Lloyd's Register of Shipping.

FRIDAY - 8 OCT 1954

As now

Docking

It is submitted that this
vessel is eligible to remain
as CLASSED.

End 

- 4 OCT 1954



© 2020

Lloyd's Register
Foundation