

1

*filed*

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel Twin Screw "CLAN MACAULAY" Report Grk. No. 20255

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

Nature of Survey First Entry When due --

\*100AL With Freeboard

3 Dks.

Cell. DB 405' 1391t, FPT 84t, APT 132t.

FK, Duct keel. ford. of machinery space, 8 BH (1 BH to 2nd Dk.), pt. Cem.

Lloyd's A & CP.

P 33', B 119', F 69'

This is a sister ship to the "CLAN MACARTHUR"

003958-003963-0148



© 2020

*filed*  
12.11.26  
*BBK*  
Lloyd's Register  
Foundation