

EA

Ship's name

"KYRIAKOULA"

Port

NWC

No.1336

Last survey date 20.7.64.

Class is subject to

NONE

S.R.L. Appendix (as before or none)

~~XXXXXX~~

Nature of present survey (afloat and in drydock)

~~XXXXXXXXXX~~

Deferred repairs to damage caused by collision.


Recommendation

SUBJECT to buckled stem bar and bow plating from 8' to 19' draught marks being specially examined and dealt with as necessary next drydocking.

As Now Subject.

IN S.R.L. APPENDIX

Shell plating etc in 1st, 2nd, 3rd and 4th below sheer in way of Nos. 1, 2, 3 & 4 stoke holds (p.s) set in. Shell and deck plating to be drill tested at next S.S. Forecastle side plating etc. (s.s) and bulwark plating etc. (s.s.a) set in.



© 2021

Lloyd's Register
Foundation

DA. 5/8/64.