

7412	270 5/8	17 3/8	88.6	123.9	519	2	20	479	270	23	TAYCO STUD LINK FOR	SAMUEL TAYLOR & SONS [BRIERLY HILL] LD.	LPH. N. 11.4.47 J.A. RELF
------	---------	--------	------	-------	-----	---	----	-----	-----	----	------------------------------	--	---------------------------

12 SEP 1946

(Received at London Office.....)

Req. 1.  
No. 5813 Port **NEWCASTLE-ON-TYNE** Date **SEPT. 9TH. 1946.**

WE request that the **MOTOR CARGO VESSEL**  
for **A & B. OTTO HILLERSTROM, SWEDEN.** by **BLYTH DRYDOCKS & SHIPBUILDING CO. LTD. BLYTH. NORTHUMBERLAND.** Building

of **6000** Tons. Length, B.P. **375'-0"** breadth, MLD. **55'-0"** depth, MLD. **SHELTER DK. 34'-3"**  
**D.W. 2ND DK. 23'-10"**  
may be Specially Surveyed while building (**LLOYDS 100A11 WITH FREEBOARD**) If for a particular term or class, state the same.

WE hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, or any variation therefrom which has been duly notified and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

No. **334** in Builder's Yard. Manufacturers of Engines **BURMEISTER & WAIN. COPENHAGEN.**

Auth'd  
No 19/9/46

~~Date~~ of Boilers FOR AND ON BEHALF OF

Signature

To the Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.

BLYTH DRY DOCKS & SHIPBUILDING CO., LTD.

*[Signature]*  
Director of Lloyd's Register

3.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—  
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

004003-004008-0092

Cofferdams have been tested by water pressure and found satisfactory. The tunnel and weather decks have been tested and found satisfactory.