



Chief Engineer Surveyor

Received from Chief Engineer Surveyor

3 OCT 1957^{4E}

NAME FIROZA

REPORT H. Kg.

No. 13694

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

Class is subject to the inboard low furnace
of the stbd. boiler being specially examined at
next MBS

Lost Rudder - Class suspended 9.56

Heavy weather repairs

is submitted action be deferred pending receipt
of Kobe reports.

L.

11 SEP 1957

see later endorsement
L.



© 2020

Lloyd's Register

004107-000115-0117
Foundation