

4E

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor..... 15 APR 1958

SHIP'S NAME..... "WINNETOU"..... REPORT..... Ham. No. 6399.


C.S. Advanced.

The main engine No. 3 cylinder jacket crack, stated on account of heavy weather, now repaired by Metalock, and the Surveyor recommends main engine No. 3 cylinder jacket Metalock repairs be re-examined by the end of 9.58.

IT IS SUBMITTED that this vessel is eligible to remain AS CLASSED, subject as recommended.



© 2020  
3.4.58.



Lloyd's Register  
Foundation

00416-00424-0057