

2 JUN 1941

Rpt. 7a.

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19

# Lloyd's Register of Shipping.

(Report on Machinery, No. 10377 Port Manchester.)

No. F.1253.

## ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by MESSRS. J. BLAKEBOROUGH & SONS LTD. of BRIGHOUSE, YORKS.  
for the M/V "LUCERNA" being repaired ~~constructed~~ by MESSRS. MANCHESTER DRYDOCKS CO. LD. of MANCHESTER.

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been ~~despatched to~~ fitted on board the M/V. "LUCERNA"

Stamp Mark.

LLOYD'S TEST.

100 lbs.

No. ELK. 4/3/41

E. Knowles

Manchester

31/3/41

Number and Description.	Quantity	Material
9 - 10" CAST IRON SLUICE VALVES.	9	CAST IRON
6 - 9"	6	do
6 - 8"	6	do
1 - 6"	1	do

Hydraulic Test:  
lbs. per square inch. 100.

Other Tests, if any. —

Dates when Inspected. 4/3/41.

38. Fee. £2-2-0. Expenses. 5/-

Payable at Manchester

004116-004124-0087



© 2020

Lloyd's Register Foundation

as now seen, so, make opening, remain as now classed in the Register Book and to have