

COPY

LLOYD'S REGISTER OF SHIPPING



Port GLASGOW

5th December, 1961.

This is to Certify that I have

examined the Machinery of the S.S. "ACAPULCO" ex "NASSAU" 15182
in the progress of Acapulco whilst the vessel was in drydock and afloat
at Glasgow on the 6th October, 1961 and subsequently on account of
repairs, TSCCL, MBS and Part CS

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also

I will Recommend that in the case of this Vessel the following
Records be made in the Supplement to the Register Book

(P & S) 11,61 MBS 12,61 now and CS with date when the
survey has been completed

and that her Machinery Classification Record be continued in the Book.

Part to (P) M.E. L.P. turbine rotor being specially examined
and salt with as necessary by 12,62 (24 month's limit) as
previously recommended.

now examined:

(S. Items only)

- and star. main condensers (tested)
- auxiliary condenser (tested)
- inboard and astern manoeuvring valves
- inboard and outboard main feed pump, port main L.O. pump.
- main S.W. circ. pump, star. inboard and outboard bilge pumps
- oil fuel unit pumps, steering machinery, windlass
- extinguishing arrangements.

Engineer Surveyor to Lloyd's Register

(R.M. NICHOLSON)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,
and that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book
published by the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof,
Surveyors, or other Officers or Agents of the Society."

150m,5,60 (MADE AND PRINTED IN ENGLAND)

Date of Committee

Decision As now subject.

W4170-004176-0068

© 2021

