

Upper Rule 330 0 Moulded .. 71 9 ✓ DEPTH, ACTUAL—Top of Floors to top of Shelter Dk. Beams Ft. Ins. 38 6
 Do. Upper Deck Beams 29 6
 Moulded depth ft 42.5 To Shelter Dk. 3 To Shelter Dk.

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

10th May, 1923.

Dear Sirs,

With reference to Mr. Langlands' First Entry Report No. 76680 on the T.S.S. "MONGOLIA", I shall be glad if he will be good enough to state whether the thickness of the fore-castle side plating is as approved, and the riveting of the seams and butts of the same in accordance with the Rule requirements.

The capacities of the fresh water tanks in Nos. 6 & 7 holds should also be stated separately so that the necessary notations can be made in the Register Book.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,
 NEWCASTLE.



© 2021

Lloyd's Register
 Foundation

IS, Bridge Deck, Angle, Bulb Angle, Plate, Tee Bulb or Channel	6	3	36	6	3	36	Angle on ditto	..
Angles on upper edge STRONG BA.	17	4	1	17	4	1	Plates DECK ST	..