

Chief Surveyors

Received from Chief Surveyors

'S NAME Steel S.S. "LADY THOMAS" Report Gl. No. 39909

For the CHIEF SHIP SURVEYOR ~~XXXXXXXXXXXXXXXXXXXX~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

of Survey

When due

❖ 100 A.1. (steel)

1 Dk (steel)

FPT 42b. APT 15b.

BK 8". 3BH. Cenz. Lloyd's A.Y.C.P. 646', 89', F23'.

Machy Aff.

The Certificate of Classification, to be endorsed  
"Cargo battens not fitted," and the same  
notation to be printed in the Register Book.



© 2021  
7-5-20

Lloyd's Register  
Foundation

004222-004229-0051