

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME SH S TEAKWOOD Rpt. hmc No. 81720

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.


("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long
Transverse No. 13072Depth "d" ✓Framing: Table No. 35690Description Longitudinal framing
as approved2nd Longitudinal No. ✓Proportions $\frac{\text{Length}}{\text{Depth}} =$ B. 17~~Deck~~ Sheerstrakeas approved

Revised Rules.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel). "Carrying Petroleum in Bulk"
2 Dk (Stl). wlb frames longitudinal framing
Cell D.B. E. B 79' 17 1/2, D.T. 37' 5 1/2, F.P.T. 17 1/2, A.P.T. 4 1/2.
F.K. 17 B.H. (8 B.H. to 2nd Dk), pt Cem, Clayds A.C.P.
P 108', B 28', F 42'. Machinery app.



© 2021

Lloyd's Register
Foundation

064222-004222-0017