

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

2nd March, 1966.

C  
MWK/CB

Dear Sirs,

Steamer "TOSA BAY"

A Report of a survey carried out at Rangoon during January has been received and at that time temporary repairs were carried out on account of damage stated to have been caused by heavy weather.

Following this survey the Committee have continued the class subject to stem and indented shell plates frames 10-11 from aft in upper fore peak tank (cement boxes), also to fractured frames No.85 (port side) and Nos.86-91 (starboard side) (temporarily repaired) and to forward and after bulkheads of deep tank (cement boxes) and shell plating in way of frame 25 in No.5 lower hold (starboard side), being specially examined and dealt with as necessary before the end of May, 1966.

Yours faithfully,

pro Clerk to the  
Classification Committee.

Messrs. World-Wide (Shipping) Ltd.,  
3, Bevis Marks,  
LONDON, E.C.3.



© 2021

Lloyd's Register  
Foundation

004405-004410-0082