

004405-004416-0083

28 FEB 1966

Ship's name "TOSA BAY"

Port

Rgn

No.

06491

Last survey date 20.1.66

Class is subject to

For conditions of class see previous endorsement.

S.R.L. Appendix (as before ~~XXXXXXXXXX~~)

Nature of present survey (afloat ~~XXXXXXXXXXXXXXXXXX~~)

Temporary repairs due to H.W. damage.

Recommendation

SUBJECT to stem and indented shell plates (Frs.10/11 from aft in upper F.P.tank (cement boxes) also to fractured frames No.85 (p.s) and Nos.86/91 (s.s) (temp.repaired) and to forward and after bulkheads of deep tank (cement boxes) and shell plating in way of frames 25 in No.5 lower hold (S.S) being specially examined and dealt with as necessary by 5,66.

As Now. Subject
Amended.

IN S.R.L. APPENDIX

Doublers fitted to 'tween deck stringer and deep tank top plating (p & s).

© 2021

TO NOTE		TRO
S. PLANS	A. RESEARCH	D. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.

4/17
24/2/66