

COPY

LLOYD'S REGISTER OF SHIPPING

No.06491



Port RANGOON

Date 21st. JANUARY 1966

This is to Certify that I have

surveyed the s.s. "TOSA BAY" 5217 gross tons of HONGKONG whilst she lay afloat at Rangoon on the 15th January 1966 and subsequently for damage alleged to have been caused by heavy weather on passage between Tokyo and Chinwangtao from 9th to 16th. November 1965 and between Chinwangtao and Singapore from 24th to 26th November 1965,

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all ^{temporary} repairs recommended by me have been completed to my satisfaction, also that I am

recommending that she be continued as classed subject to (a) the forepeak (b) stb'd ship's side frames Nos.86/91 and port ship's side frame No.85 of deep tank in No.3 Lower Hold (c) starboard side of after bulkhead in deep tank of No.3 Lower Hold and (d) starboard shell plating in way of web frame No.25 being specially examined & dealt with at next drydocking by 5/66, and also subject to any outstanding condition of class being dealt with as previously recommended.

(R.D. HORMUSJEE)

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS	Annual Survey	SS	Hull Special Survey
BiS	Biennial Survey	SS(Dr)	Hull Special Survey (Drilling)
DS	Docking Survey	SS(M)	Hull Special Survey (Modified)
NS	Cargo Battens not fitted (No Sparring)	CSH	Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society".

N. Cert. B 100,m,2,65 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register Foundation

004405 - 004410 - 0086