

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex  
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

26th April, 1966.

C.  
DNS/DET

Dear Sirs,

S.S. "SAFINA-E-JAMHOORIYAT"

With reference to your memorandum of the 14th March, I shall be glad to learn whether you are yet in a position to state what definite arrangements have been made for the Special Survey to be carried out, by the end of next month.

Following the survey carried out by the Dundee Surveyors between the 4th and 11th March, the Committee have continued the vessel's class subject to 15 fathoms of chain cable (starboard side) being supplied at the earliest opportunity, first 45 fathoms of chain cable (starboard side) being specially examined and tested by the Special Survey, starboard boiler not to be used until repairs to butt strap are satisfactorily completed and to the attached port bilge pump water cylinder valve chest flange being specially examined by the end of March 1967.

The ship's class is also at present subject to indented shell plating abreast No.4 hold (port side) and shell plates G.A.2 (port side from forward) in way of No.1 hold between frames 161/163 being specially examined and dealt with as necessary next drydocking.

Please inform the Owners accordingly.

Lloyd's Register  
Foundation

004405-004410-01882



-2-

The Owners' intentions regarding  
the main Boiler Survey, which became due  
at the end of March last, will also be  
appreciated.

Yours faithfully,

pro Classification Manager

The Surveyors,  
KARACHI.



© 2021

Lloyd's Register  
Foundation

0188  $\frac{2}{2}$