



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Powell Duffryn House, Adelaide Street, Swansea

Telegrams: Lloyd's Register

RECEIVED 9th August, 1950.

Telephone: Swansea 3860

Reference

S.....

Dear Sir,

10 AUG 1950  
ANGD  
T.S.M.S. "SAN PEDRO".

With reference to your letter of the 8th instant respecting the above vessel we beg to inform you that the Safety Valves of the oil fired boilers were not adjusted by us at the time of the survey of the exhaust gas boilers as per our Report No. 24515. At that time the Chief Engineer stated that the oil fired boilers had been previously examined. The vessel was sailing immediately and therefore the deferred reports were not obtained for verification of the position.

It is regretted this was not done so that the items for completion of the D.B.S. could have been entered in our Report No. 24515 instead of referring to the exhaust gas boilers only.

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,  
Per:-

The Secretary,  
LONDON.

© 2021

Lloyd's Register  
Foundation

E.

Referred to Mr. Perris.

*Handwritten signature*

*Notes  
10/18/17*



© 2021  
Lloyd's Register  
Foundation

RECEIVED  
Royal Doulton House, Vordale Street, Sturges  
LONDON  
CALLED WITH THE BIRTH COMPANY'S REGISTER  
ROAD 2, REGISLER OF SHIBBIC