



# Lloyd's Register of Shipping.

HARBOUR APPROACH ROAD

P. O. Box 109 63

Visakhapatnam-1, 29th July, 1966.

Reference

**MISC:**

Dear Sir,

S.S. "GALAXIAS"

We enclose a copy of a letter received from the Deputy Conservator, Visakhapatnam Port Trust, which you will find self-explanatory.

Action taken according to Sub Section (2) of the Indian Ports Act means that the ship will be towed out by the Port authorities and anchored outside Port limits (off Visakhapatnam approximately 2-3 miles from shore).

In view of the fact that to date no action has been taken regarding commencement of repairs, there is a possibility that the ship may be towed outside port limits. Due to this, we would be grateful if you could advise us as to the Society's position should this occur, i.e., whether classification should be suspended pending repairs and if so in what way should the Captain and Owners be informed. Details of damage sustained given in our Damage Report No.945 forwarded to you on 26th July, 1966.

Yours faithfully,  
For The Surveyors.

(C. FERRIER).

The Secretary,  
L o n d o n.

Encl:

CF/pvr:



© 2020

Lloyd's Register  
Foundation

004486-004488-0310

REPORTS  
CLASSING

Card

Submit notation be assigned if  
Repairs required - Bless suspended

MB 5/8/66  
Lust SK



© 2020

Lloyd's Register  
Foundation