

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

19th January, 1966

C.

DD/BN

Dear Sirs,

S.S. "APJ AMBAR"

With reference to your letter dated 8th December, I shall be glad to learn what early and definite arrangements the Owners propose to make for the Screwshaft Survey and the Boiler Surveys to be carried out, and for the verification of the equipment, as this ship does not appear to have been reported under survey by the Bombay Surveyors as intimated by you.

As a result of a survey carried out by the Cochin Surveyor during November, the Committee have continued the ship's class subject, inter alia, to the No.4 hold being specially examined for fire damage on the ship's arrival at Bombay or your port ~~from~~ her present voyage. It is concluded that this matter will receive the necessary attention.

Yours faithfully,

cc Bom

Assistant Clerk to the
Classification Committee.

The Surveyors,
CALCUTTA



© 2020

Lloyd's Register
Foundation

004488-004488-0347