

COPY

FROM APEEJAY LINES

OWNERS SURREBDRA OVERSEAS LIMITED

TECH/LRS/10/11806

47 Hide Road Extension,
CALCUTTA 27.

The Secretary,
Lloyd's Register of Shipping,
1, Fairlie Place,
CALCUTTA.

Dear Sir,

s.s. "A P J - A M B A R"

We are in receipt of your letter of 15th Jan 1965 with regard to the outstanding items to complete the C.S. cycle.

The item concerning main LP turbine, reduction gear and hydraulic coupling will remain in abeyance until such time as the Exhaust Turbine is repaired.. The repairs to the Turbine will probably include some blading and the facilities for such work at an Indian Port are meagre. 1/384

It is understood that following items have been dealt with by Mr. Madhok at this time:-

Holding down bolts and chocks
Engine tested working
Both lubricating oil pumps
Pumping arrangements

Part of the electrical equipment remains to be done, as repairs have to be carried out on some circuits due to poor insulation testing results. It is hoped to complete repairs to the faulty circuits when Vessel returns to Calcutta with the next few months; at conclusion of rice shipment season from Burma.

2f

Yours faithfully,
for APEEJAY LINES,

Owners: Surrendra Overseas Limited.

sd/ R.K. AGARWAL.

004486-004488-0384

