

## LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name "INDIAN ENDEAVOUR"

Official No. 180162.

Port of Registry CALCUTTA.

This ship has been under survey at LIVERPOOL.

on 29th APRIL 1955. and the following alterations to the conditions of assignment of loadlines have now been effected:

2 additional s.v. vents to settling tank spaces (1p & 1s), in tween deck, have been fitted on foreboard deck, 5' dia and 30" above deck to opening. Vents fitted with gauges and hinged steel flaps, secured by butterfly nuts.

<sup>Composite</sup>  
A 3" bow stem valve has been fitted on ship's side (S.S.), discharging below foreboard deck, taking discharge pipe from washbasins in passenger cabins above foreboard deck.

J. M. Miller

noted  
S

11 MAY 1955

A copy of this Report has been placed on board.



© 2020

Lloyd's Register  
Foundation