



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Hamburg 1, Ballindamm 25

718/GS/GA

Telegrams: Surveyors, Hamburg 2nd February, 1955.

Telephone No. 33 35 39

33 88 08

Reference:

Classn(S)

RECEIVED

4 FEB 1955

Ans'd

Dear Sir,

"INDIAN ENDEAVOUR" - Hamburg Report No. 3570

In reply to your Classing letter dated 21st instant, we have to advise you that indented shell plates No. 7 from aft (port side) in 2nd and 3rd strakes below sheer have been dealt with on the occasion of this survey: this has been entered on our Report 8 under "Wear & Tear Repairs - shell plates faired in place p.s." and which were numbered from forward, i.e. H 15 and I 15.


We regret that this was not made clear.

Yours faithfully,  
The Surveyors,

Per:

*Guilher Schneider*

The Secretary  
LONDON.



Lloyd's Register  
Foundation

004489-004495-0155

DELETE FROM S.R.L.

Endeavour (grounding) ✓

ST.

CLASSIFICATION

H ll

notes RSP 7/2/55

Went down!



© 2020

Lloyd's Register  
Foundation