

Received from Chief Ship Surveyor 19 JAN 1955

SHIP'S NAME "INDIAN ENDEAVOUR" REPORT Ham. No. 3570

Outstanding Conditions of Class: Subject to indented shell plating in 1st & 2nd below sheer (p.s.f.) being permanently repaired by next Special Survey.

ACTION is DEFERRED for examination in dry dock after grounding, and Special Survey.

Endorsement of Class (B) (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (B) due 1,54 - postponement of Special Survey until ship's return to Hamburg approved 29.4.54. General Examination held Ham. 3,54.

Nature of Present Survey: (Afloat and in dry dock)

Special Survey: Conversion to oil burning: Damage (grounding).

Special Features: ✓

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)

Work to be completed by:

Recommendation:

SUBMITTED record of docking 11,54 and Notation of 'ss.Ham. 11,54' be assigned, without special condition.) Without.

11,54 Ham.)
ss.Ham. 11,54.)

te ENDORSEMENT OF CLASS (B).
Shell plates No. 7 from 1st (p.s.f.) See letter
in 2nd & 3rd below sheer indented. dated 2/2/55

OFFICE NOTE:- N.S. 9.3.54.

DELETE FROM S.R.L.
Drydocking (grounding) ✓

✓ INSERT IN R.B.
"Fitted for oil fuel 11,54 F.P. above 150°F"
Radar.



© 2020

Lloyd's Register
Foundation

E.T.O.



Reference:
SHIP

REPORT No. 5870
SHIP'S NAME "INDIAN ENDEAVOUR"

See letter dated 2/2/55

X
2/11

IT IS FURTHER SUBMITTED the Surveyors be advised it is concluded the indented shell plates No.7 from aft (p.s.) in 2nd & 3rd strakes below sheer, previously recorded as an Endorsement of Class (B), still remain to be dealt with.

R.S.P
15/1/55

Special Survey: Conversion to oil burning; Damage (grounding).
Nature of Present Survey: (Afloat and in dry dock)

Interim Certificate in order (Yes-No-None)

Outstanding: (If any for S.S. or A.S.)

SUBMITTED record of booking 11,54 and notation of 'as Ham. 11,54' as assigned, without special condition.

11,54 Ham.
as Ham. 11,54

ENDORSEMENT OF CLASS (B).
Shell plates No. 7 from aft in 2nd & 3rd strakes below sheer indented.

OFFICE NOTE: - N.S. 9.3.54.

DETAILS FROM S.S. (p.s.)
Drydocking (grounding)

© 2020



Lloyd's Register
Foundation

E.N.C.