

COMMITTEE LDN
TX154 TCKA55 CDS106
CALCUTTA 30/29 27 1630

4216

CALCUTTA

RECEIVED
28 JUN 1966

LT
COMMITTEE LONDON

INDIAN ENDEAVOUR SUSPECT LP PISTONROD BENT INWAYOF CROSSHEAD
NOW REMOVING TO WORKSHOP FOR CHECKING STOP WOULD APPRECIATE
YOUR DETAILED ADVICES ON THERMAL STRAIGHTENING OF PISTONROD
INDIAWARDS

CVL LP

SENT 0042/28 RCR +
COMMITTEE LDN

CABLE IN



© 2020

Lloyd's Register
Foundation

004489-004495-0189

Report
Chapman.

224

Indian Endeavour neural suggest
straighten iP not without heating of
practically, otherwise do not exceed 650°C .
and crack detect on completion.

Inst. 28-6-66



© 2020

Lloyd's Register
Foundation