

Ship's Name SS/M/ "INDIAN ENDEAVOUR"  
LR 516027 Gross tons 7306  
Is there a rpt. 9? Yes Port Calcutta Rpt. No. 1746  
No. of visits 2 First date 4/5/65 Last date 12/5/65  
Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? - Last rpt. (H.Q. only) CBO 5860  
Date of completing rpt. 14/5/65 Surveyed at, if different from Port above  
Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D. -  
Has a Load Line Survey been held? Yes, Annual Freeboard Marks verified Yes  
State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) -  
Survey fees Damage fee Expenses Rs. 30/-  
Spl. Examination Rs. 200/- S.A. fee Rs. 100/-

I have surveyed the above ship in accordance with the Rules for Annual Load Line Survey and Examination of No.6 (P&S) Double Bottom tanks.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

#### Condition of Class No.234

No.6 Double Bottom top frames and reverse bars etc. to examine annually.

#### Now Done.

No.6 DB tanks (P&S) now examined internally and found to remain efficient.

It is recommended that the notation for No.6 DB (P&S) tanks to be examined annually be retained.

#### SRL Appendix No.15

Shell plate H.17 (ss) set in.

Not examined at this time.

I recommend that this ship remain as classed ~~with~~ without fresh record of ~~xxxxxx~~ Survey, subject to No.6 Double Bottom tanks (P&S) being examined annually as previously recommended.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee

WEDNESDAY 23 JUN 1965

Minute

As now, subject (h & m)  
SPS 10.64

D. VINCENT.  
Surveyor to Lloyd's Register of Shipping

FOR CHAIRMAN  
CLASSN. CTTEE

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT