

120.86
22.42

Long Bridge Deck }
Beam at side to top of keel }

Port belonging to

11. 10. 22

Received from Chief Surveyors

12 OCT. 1922

$\frac{1}{5}$ Lossie

Report

Liv.

No. 82483

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

shall have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case."—Extract from Sub-Committee's Report, 24/5/22.)


1st. First Entry.

When due

Vessel still laid up.

Mr. J. A. Hill
note.

13. 10. 22



© 2021

Lloyd's Register
Foundation

004564-004572-0035