

EA

13 MAY 1963

Ship's name "STANLAND" Port GIB No. 4670
Class is subject to Last survey date 16.3.63.

indented side shell plating etc. in way of No.1 hold (p.s) and indented and set in shell plates F.7, G.7,8 & 14, J.8 (p.s) F.12 & 13, G.11, H.11, J.15 & 16 (s.s) all from forward being repaired at the next drydocking.

S.R.L. Appendix (as before ~~or vice versa~~)

Nature of present survey (afloat and ~~in drydock~~)

Permanent/temporary repairs to H.W. damage.

Recommendation SUBJECT as above and to repairs in way of after end of No.3A hatch (p.s) being specially examined and dealt with as necessary by 6,63.

As Now Subject.

~~IN S.R.L.APPENDIX~~
Indented shellplates (p & s).



© 2021

Lloyd's Register
Foundation