

COPY.

. Nicholas, Esq.,
 Yds Register of Shipping,
 ord Street,
THAMPTON.

ar Sir,

S.M. "DORABELLA" ex L.C.I. (L)

In reply to the points raised in the letter from Lloyds
 ister, Glasgow, of the 7th July - Ref T24/E1.

Air and Sounding pipes were examined and found satisfactory,
 the Sounding pipes have a welded doubler on the Shell
 underneath.

Seacocks and Valves were all examined and found in good
 condition in January, 1949.

Holding down bolts all tested and found in good condition.

All electrical circuits were Megger tested and found
 to be satisfactory.

As regards the class for this vessel. I am informed
 Mr. Channer that Lieut. Col. The Hon. Eyres Mauncell applied
 Cross Channel and Coasting Service (British) and that if
 ere is any misunderstanding on this point, that is what is
 quired.

Yours faithfully,

D. McQUEEN



© 2021

Lloyd's Register
 Foundation

004564-004572-0160