

(2) 60 fathoms of chain cable' - not supplied yet.

Received from Chief Ship Surveyor.....

24 JUL 1961

P'S NAME "OCEAN ENDEAVOUR" REPORT Krh. No. 3308

GB

standing Conditions of Class: SUBJECT to bottom shell plate A.5 (p.s.a) being specially examined and dealt with as necessary by the Special Survey also to an anchor joining shackle being verified and a bower anchor and 60 fathoms of chain cable being supplied at the earliest opportunity.

ACTION is DEFERRED for Equipment.

S.L. Appendix. (As before or None)

ure of Present Survey: (Afloat and in dry dock)


Supply and verification of a bower anchor.

commendation:

SUBMITTED the ship is eligible to continue as classed, subject to bottom shell plate A.5 (p.s.a) being specially examined and dealt with as necessary by the Special Survey/also to an anchor joining shackle being verified and 60 fathoms of chain cable being supplied at the earliest opportunity, without other condition but further ACTION continue to be DEFERRED for Equipment.

SUBJECT
WITHOUT.

IN S.R.L. APPENDIX.
Indents in 'H' strake (p.s.).



© 2021

Lloyd's Register
Foundation