

CONSULATE

M/M.4661

WRECK
SECTION

1001

WRECKED

J	J
F	F
M	M
A	A

M	M
JE	JE
JY	JY
A	A
S	S
O	O
N	N
D	



© 2020

Lloyd's Register
Foundation

004653-004661-0128

CERT ISSUED

when small quantities
etc up to 100 lbs

5	513253	CONSULATE	8532	★100A1	1941-7	A. Stephen & Sons Ltd.—Gls	M Ref CSD	Oil 2SA 6Cy. 670 × 8320 mm
N	SVXW	ex Gloucester-66	5022	with freeboard	473' 0" 60' 4" 27' 5"		5 Ho 60', 72½', 30', 74½', 72'	6400bhp Duxford
M		Embajada Cia. Nav. S.A.	9330	★LMC	450' 0" 60' 0" 39' 6"		G.197315 B.190880 In.268060	Barclay, Curle & Co. Ltd.
L	Df Esd	Piræus		★Lloyd's RMC	F40' 2 dks, 3rd dk clear of mchy. space		1 Ha (stl) (18' × 16')	AuxB 100tb
G	Gc Rdr	Greek		MN(1294)	EL c†2½"SQ	R 6 divisional WTBHs in upr 'tween dks	4 Ha (w) (32', 21½', 32', 26½' × 20')	3 × 300kW 220V d.c.
F	RTM/v					Coll BH to W dks 6 to 2nd dk	15W Der 2(10) 2(8½) 10(5)	
						rf 3" DK 56' fwd of mchy. space	WB1302t	

To Be Broken Up

C.S. (MCHY)

* Screw shaft in accordance with C/1002
provided crack detected next TS due 10.65.

SEE NOTE S.R.L. (MAUMY)

provided crack checked with 15 and 10 ft.									
LAST SPECIAL SURVEY	HULL					MCHY.	CS	CS	
		7/61					7/61	9.65	
LAST DOCKING SURVEY	10/61	9.63	10.64	8.65	2/66				
" BOILER "	/	/	/	/					
" AUX/DONKEY BLR "	10/62	3.64	8.65						
" STM. GEN. "	/	/	/						
* SCREWSHAFT	CL 10/62	8.65							
" STEAMPIPES "	/								
" WEAR DOWN ON STERN BUSH	3/32"	290"	3/32"	RB 10 1/16"	3/32"				
FIRE EQUIPMENT SURVEY DUE	5/4/67								

7 Broken up.

© 2020

Lloyd's Register
Foundation