

PT

22 OCT 1965

Ship's name "GLOUCESTER"

Port HTN

No 78

Last survey date 11.4.65

Class is subject to

indented shell plate J.1 (p.s.f) and internals in way, to wasted bulkheads 1/2 and 2/3 in way of upper 'tween deck and to No.4 upper 'tween deck chocks being specially examined and dealt with as necessary by the Special Survey.

S.R.L. Appendix (as before of ~~XXXXXX~~)

Surveys due

SPECIAL SURVEY (D) due 7.65. Postponement until 7.66 approved 8.2.65 subject to a G.E. in drydock at Mtl. July or August '65.

Nature of present survey (afloat and in drydock) ~~XXXXXXXXXXXX~~

lower  
Temporary repairs to wasted shell plating in No.5/hold (p.s).

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by

Recommendation SUBJECT as above, and to holed shell plate C.14 (p.s) in way of No.5 lower hold (temp. repaired) being specially examined and dealt with with as necessary by 10.65. ~~but ACTION be DEFERRED for Special Survey.~~

SUBJECT.

IN S.R.L. APPENDIX

Shell seam of 'J' & 'K' strakes in way of frs.109/111 (p.s.f) indented.  
(Sternframe at top gudgeon E.W. 7.61).  
Indents in shell plating (p & s).

© 2020

Lloyd's Register  
Foundation