


LLOYD'S REGISTER OF SHIPPING



Port Hamilton, Bermuda

11th April, 1965.

This is to Certify that I have
Surveyed the British M.S. "GLOUCESTER" Gross Tons 8532
of London as she lay afloat at No. 7 Dock in Hamilton Harbour
in a partially laden condition relative to a leak in hull of
No. 5 Hold which developed on this voyage,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend that she be allowed to remain as classed subject
to this shell plate being dealt with as necessary at next
dry docking within 6 months and subject to any other out-
standing condition of Class being dealt with as previously
recommended

J. H. Parker

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS (Dr) Hull Special Survey (Drilling)
SS (M) Hull Special Survey (Modified)
SS (P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."