

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

4th May, 1964

C.
DHGK/MRN

Dear Sirs,

Motorship "GLOUCESTER"

The Report of a survey held at Durban in March, has now been received in this Office.

At this time some Metalock repairs were carried out to main engine No.4 unit bottle guide casting, and it was recommended that these repairs should be specially examined by the end of September 1964.

I think it well to add that class is subject also to:-

- 1) Repairs to main engine No.4 unit "A" frame, diaphragm plate and crank case being specially examined by the end of June 1964.
- 2) Repairs to the water jacket, bedplate and crankcase in way of No.6 unit of starboard forward generator engine being specially examined by the end of June 1964.
- 3) Repairs to port aft generator engine being specially examined by the end of August 1964.

Yours faithfully,

Deputy Clerk to the
Classification Committee

The Federal Steam Navigation, Ltd.,
138, Leadenhall Street,
LONDON, E.C.3.

© 2020

Lloyd's Register
Foundation

004653-004661-0205