

30 APR 1964

Ship's name Gloucester

Port Durban

No. 10762

Last survey date 29/3/64

Class is subject to

1. Repairs to M.E. N°4 unit 'A' frame, diaphragm plate & crankcase being specially examined by 6.64.
2. Repairs to the water jacket, bedplate & crankcase in way of N°6 unit of starboard forward generator engine being specially examined by 6.64
3. Repairs to P.A. generator engine being specially examined by 8.64

M.E. N°4 unit bottle guide castings  
broken now repaired by metalock  
(3/64) surveyor recommends  
be specially examined by 9.64

*It is submitted that this vessel is eligible to remain as **CLASSED**.* subject to above and as recommended.

40g  
29/4/64.



© 2020

Lloyd's Register  
Foundation

004653-004661-0206

x