



© 2020

Lloyd's Register
Foundation

WILTON-FIJENOORD
SCHIEDAM - HOLLAND
COPYRIGHT WF NADruk VERBODEN

Tomar

Crack after veeding out stb. side
coupling flange of stern frame.

Bij nabestelling opgeven Neg. Nr. N246 / 3
Datum Order Nr. 5131

W

2/MS	Tomar	© 2020
TO/CO/...	Rot.	56874
Dated	9/63	Lloyd's Register Foundation
SUBJECT:-		

004684-004692-0236